

Note: Dimensions are nominal measurements only

SPECIFICATIONS	
RECOMMENDED USE	Domestic
MATERIAL	Solid Brass
TEMPERATURE RATING	Maximum continuous working temperature 75°C If the water temperature exceeds 75°C,an approved tempering valve must be fitted
PRESSURE RATING	Recommended minimum working pressure 150kPa Recommended maximum working pressure 500kPa Hot and cold water inlet pressure should be equal
SUITABLE HOT WATER UNITS	Storage tank: Yes Continuous Flow: Yes Gravity Feed: Not suitable


INSTALLATION GUIDE

Note: This product must be installed by a licensed plumber. This is a general installation guide - there are many factors that are involved that can alter the installation method. This product install must comply with AS/NZS 3500.



- 1) Check that the male brass thread installed in the wall is the correct length. Cut to length if required ensuring end face is square. Apply thread tape to the thread.
- 2) Slide the cover plate onto the arm. Carefully screw the arm onto the brass thread until the threaded end is adjacent to the wall/tile or ceiling face and the outlet is facing down. Do not tighten and be careful not to damage the decorative finish. Push the cover plate until it meets the wall/ceiling face.
- 3) Refer to individual product guide for installation of shower head.

Note: To ensure the shower head is plumb please see the following instructions below;





Regularly clean with

mild liquid detergent

or soap and water.



